

From: Olsen, Peter M
Sent: Friday, 9 March 2007 1:54 PM
To: CLEMESHA Mary <Mary_Clemesha@rta.nsw.gov.au>
Subject: RE: Faulty Safety Switch

Mary,

Safety switch tripped again twice this week. Lloyd Cuerel said they had not done anything as it is now an RTA responsibility.

I believe the transformer was replaced last time. Can you get the safety switch replaced as well please. Maybe it is faulty.

Regards
Peter Olsen

From: Olsen, Peter M
Sent: Thursday, 8 February 2007 1:30 PM
To: CLEMESHA Mary <Mary_Clemesha@rta.nsw.gov.au>
Cc: 'lcuerel@energy.com.au'
Subject: RE: Faulty Safety Switch
Dear Mary,

As discussed earlier the safety switch on the same school zone flashing lights tripped again and the lights were not working this morning. That is now the fourth time.

I spoke to Lloyd Cuerel from Energy Australia and he said he would try to get someone to have a look at the RCD switch.

If possible it would be appreciated if the switch could be reset prior to 2.30pm so that the lights work for this afternoon's school zone period.

Regards
Peter Olsen.

From: Olsen, Peter M
Sent: Monday, 5 February 2007 8:52 AM
To: CLEMESHA Mary <Mary_Clemesha@rta.nsw.gov.au>
Subject: Faulty Safety Switch

The safety switch on the sign on Belmore Rd near Evans St tripped again this morning and as a result the lights were not flashing. I rang the 131700 number and reported it. I also asked them to get someone to check the safety switch and/or the transformer, as this is the third time it has happened.

Could you please follow up and make sure it is checked out properly, as it is affecting the apparent reliability of the lights.

I note that the earth leakage switch only detects conditions between it and the transformer, not from the transformer to the sign or on the sign itself as that is completely isolated from the safety switch by the transformer. Thus the problem cannot be with my controller.

From: Olsen, Peter M
Sent: Thursday, 7 December 2006 12:12 PM
To: CLEMESHA Mary <Mary_Clemesha@rta.nsw.gov.au>
Subject: 40kmh School Zone Lights

Dear Mary,

I refer our conversation of last Tuesday and confirm that the problem with the lights on Belmore Rd at the south end of Peakhurst West Public School was the tripping of the Energy Australia earth leakage safety switch. That problem occurred with the same sign on a previous occasion also.